Rs. 9702.67 crores outlay has been provided for ONGC and OIL for the Plan period.

(c) Against an outlay of Rs. 180,000 crores for the entire Public Sector, the outlay for exploration and production in the VII Plan is Rs. 9702.67 crores.

(d) Oil exploration 'being probab-listic in nature, it is not possible to state with a degree of certitude that self sufficiency would be achieved through a given outlay.

Diminishing: capacity of Bon.bay High

729. DR. BAPU KALDATE: SHRI M. S. GURUPADASWAMY:

Will the Minister of PETROLEUM AND NATURAL GAS be pleased to state:

(a) whether it is a fact that the capacity of Bonibay High has been regularly diminishing since the last fire;

(b) if so, what is the present output per day of Bombay High;

(c) whether any additional steps have been taken to keep the original production; and

(d) if so, what are the details thereof?

THE MINISTER OF STATE OF THE MINISTRY OF PETROLEUM AND NATURAL GAS (SHRI CHANDRA SHEKHAR SINGH); (a) and (b) No, Sir. The fire on Sagar Vikas took place in July 1982. During the last three years the production of crude oil from Bombay offshore has increased as follows:—

Year	Production (MT)	Average daily Production (000 Tonnes)
1982-83	12·88	35
1983-84	17·39	48
1984-85	20·14	55
1985-86 (anticipated)	20·61	56

(c) and (d) Do not arise.

Problems in Drilling- at Bodra

730. SHRI MOSTAFA BIN QUASEM: Will the Minister of PETROLEUM AND NATURAL GAS ba pleased to state:

(a) whether the Oil and Natural Gas Commission drilling at Bodra in 24 Parganas, with the help of the Russians, has developed some prob lems;

(b) if so, what are the details of the said problems; and

(c) what efforts have been made 'by Government to solve the problems and the results achieved so far in thi» regard?

THE MINISTER OF STATE OF THE MINISTRY OF PETROLEUM AND NATURAL GAS (SHRI CHANDRA SHEKHAR SINGH): (a) Yes Sir.

(b) During drilling of Bodra well No. 2 beyond the depth of 3760 metres, simultaneous mud loss and high pressure were encountered. The problem was overcome by cement squeeze jobs and drilling was carried on to a depth of 4324 metres when the drill string got stuck and could not be released despite efforts. The hole wa» deviated from 3780 metres to 4170